

## Zedi SilverJack Bulletin: SJ8000 Extended Shutdown Procedure

If you're planning to shut down your Zedi SilverJack 8000 (SJ8000) on a well for an extended period of time (for one day or more), follow this procedure to ensure that the equipment stays secured and undamaged.

1. If the Lift System is operating, stop the pump on the local controller.
2. Manually stroke the Lift System to the bottom of its stroke. This can be done on the local controller or on the pump.
3. Bleed the piston accumulator on the local controller.
4. Manually stroke the Lift System to the bottom of its stroke again. This makes sure that all of the Lift System's polished rods are retracted and protected from the elements.
5. Stop the motor on the local controller.
6. Shutdown the controller.



Follow this procedure if you are shutting down your SJ8000 for an extended period of time. Failure to do so may damage equipment and void warranty.